UTAH DEPARTMENT OF ENVIRONMENTAL QUALITY WATER QUALITY

STATE OF UTAH DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF WATER QUALITY

EXPEDITED SETTLEMENT OFFER

This Expedited Settlement Offer ("ESO"), is entered into by and between the Director of the Division of Water Quality ("Director") and Lake Point Vistas, L.C. ("Owner/Operator"), jointly referred to herein as the "Parties," pursuant to the Director's authority under the Utah Water Quality Act, Utah Code §§ 19-5-111, 19-5-115, Utah Administrative Code (UAC) R317-1-8 and R317-8-3.9.

- 1. Owner/Operator is a "person" as that term is defined in Utah Code § 19-1-103(4).
- 2. Owner/Operator is conducting "construction activity" at Bridlewalk Phase 4 (the "Project").
- 3. The Director issued the General Permit for Storm Water Discharges from Construction Activities UTRC00000 authorizing owners/operators of construction activities to discharge in accordance with specific terms, conditions and best management practices as provided for in the Permit and UAC R317-8-11. Owner/Operator obtained coverage for the Project under UTRC00000 and was assigned UPDES Permits No.: UTRC01785 and UTRC06339, making the Owner/Operator responsible for compliance with UTRC00000. (UTRC00000 and the Owner's/Operator's specific coverage are referred to collectively herein after as ("the Permit")).
- 4. An ESO may be used in enforcement cases in lieu of the penalty process in when violations are readily identifiable, readily correctable, and do not cause significant harm to human health or the environment. See UAC R317-1-8.3 and -8.6.
- 5. The attached Expedited Settlement Offer Deficiencies Form ("ESODF"), incorporated herein by reference, includes findings which specify the conditions in violation of the Permit observed at the Project during an on-site inspection conducted on January 27, 2023. The ESODF is in lieu of an initial order, notice of violation or notice of agency action to facilitate the purposes described hereinafter.
- 6. The Parties voluntarily enter into this ESO in order to: identify the actions necessary to correct the deficiencies observed at the Project; determine the amount of the civil penalty appropriate for the violation(s) based on the deficiencies alleged; and to conclude this matter without the necessity of further administrative or judicial proceedings.
- 7. Owner/Operator agrees that a penalty in the amount of \$4,160.00 is appropriate based on the circumstances specified herein. This ESO is subject to a thirty (30) day notice and comment period as provided for in UAC R317-8-1.9. The Parties each reserve the right to withdraw from this ESO if comments received during the notice period result in a modification to the terms and conditions.
- 8. By accepting this ESO, Owner/Operator neither admits nor denies the findings, violations or deficiencies specified herein.

UTAH DEPARTMENT OF ENVIRONMENTAL QUALITY WATER QUALITY

STATE OF UTAH DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF WATER QUALITY

EXPEDITED SETTLEMENT OFFER

- 9. Owner/Operator agrees to the terms, conditions and requirements of this ESO. By signing this ESO, Operator understands, acknowledges and agrees that it waives: (1) the opportunity for an administrative hearing pursuant to Utah Code § 19-1-301; (2) the right to contest the finding(s) in the ESODF and the penalty amount specified herein; and (3) the opportunity for judicial review.
- 10. Owner/Operator certifies that all deficiencies identified herein have been corrected and that the Project is currently in full compliance with the terms and provisions of the Permit. Additionally, Owner/Operator has attached to this ESO: (1) a written description detailing how the deficiencies were corrected; and (2) representative photographs documenting the current conditions and the associated Best Management Practices implemented at the Project.
- 11. The Parties mutually agree that this ESO is entered in good faith and is an appropriate means to resolve the matters specified herein.
- 12. This ESO will be final after the thirty (30) day notice and comment period on the date the Director signs the ESO, at which time the civil penalty takes effect.
- 13. Owner/Operator agrees that within thirty (30) calendar days of receiving the signed and final ESO and invoice information from the Division of Water Quality ("Division"), Owner/Operator shall submit payment in accordance with the instructions attached to the invoice, in the amount specified in paragraph 7 above.
- 14. The violations described herein will constitute part of Owner's/Operator's compliance history where such history is relevant, including any subsequent violations. Owner/Operator understands and agrees that this ESO is not and cannot be raised as a defense to any other action to enforce any federal, state or local law.
- 15. This ESO, when final, is binding upon Owner/Operator and any corporate subsidiaries or parents, their officers, directors, employees, successors in interest, and assigns. The undersigned warrants that it is authorized to legally bind their respective principals to this ESO.





STATE OF UTAH DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF WATER QUALITY

EXPEDITED SETTLEMENT OFFER

FOR THE UTAH DIVISION OF WATER QUALITY

By:	John K. Mackey, P.E. Director, Utah Division of Water	Quality
Date:		(Effective Date)
FOR I	LAKE POINT VISTAS, L.C.	
By:	Alghe &	
Title:	Maneiger	
Date:	8-17-23	

DWQ-2023-006047

EQ_Docs/DWQ/Compliance and Enforcement/Lake Point Vistas, L.C./2023 ESO Bridlewalk Phase 4 UTRC06339/2023-04 ESO Issuance Lake Point Vistas UTRC06339



		Silver Leaf SWPPP CGP			
Site Name:	Bridlewalk Phase 4 1985 E Cluff Ln, Lake Point, UT 84674	Inspector:	Daniel Andrews		
Permit #:	UTRC06339	Inspection Frequency:	Bi-weekly -		
Date of Visit:	Aug 22, 2023, 11:01:59 AM	Last Rain Event Friday, August 18, 2023, 0.04	Last Precipitation 48h Foreca Thursday, August 17, 2023, 0.82* 85% Chance of		

SWPPP Sign

1) Is the SWPPP Sign posted and visible onsite?







2) Is the site notice, NOI and other required permits attached to the sign?



NO

2A) Date of NOI Expiration

02/05/24

2B) Other Permit Type and and Expiration if applicable:

N/a

3) Is the site notice QR code active and the current site contact information posted on the sign?





Site Contact information: Please fill out questions 4a-4c on who the current site contact is for the site. This is the responsible person for the site and overseeing the SWPPP. This information could be different than the question regarding who communication and review of this inspection were done with. *Site Contact information should be current on the sign if changes are made.

4A) Please list the current site contact Name:

Howard

4B) Please list the current site contact phone number:

801-859-9449

4C) Please list the current site contact role;

Superintendent

4C) Other:

N/a

Site Overview



Silver Leaf SWPPP CGP							
Site Name:	Bridlewalk Phase 4 1585 E Chiff En, Luke Point, UT 84074	Inspector:	Daniel Andrews				
Permit #:	UTRC06339	Inspection Frequency:	Bi-weekly -				
Date of Visit:	Aug 22, 2023, 11:01:59 AM	Last Rain Event Friday, August 18, 2023, 0.0"	Last Precipitation Thursday, August 17, 2023, 9,82"	48h Forecast 85% Chance of Rain			

5) Current phase of construction

Mass Grading and Excavation

A WEST TO SERVICE AND ADDRESS OF THE PARTY O

Grubbing and Grading

Pre-Construction- NO activity

Utility Work, Curbs and Gutter - Storm Drain Box installation

Road - Base and Asphalt

Rough Framing

Exterior Construction

Finishes and Fixtures - Landscaping

Closeout- NOT ready - Occupancy

Land development is complete. Sweeping continues regularly, Lots 401 & 402 have been sold.

N/a

Silt Fence

Fiber Rolls

Curb Cutback

Berms

Vegetation or stabilized solls

Check Dams

Elevation

Drainage Swales

N/A

Retaining Wall

N/a

Yes No



Yes No N/A

Yes No

Yes No N/A

What Phase(s) of the project are active? Notes regarding activity and Lots:

Completed Phase(s) Indicate here:

6) Identify the perimeter controls onsite

Other perimeter control notes

- 7) Is there evidence of sediment leaving the site? (check roads, dirt ramps, sidewalks, and parking areas)
- 8) Are track out controls installed and maintained?
- 9) Are drain inlets installed on site?
- 9A) If yes are inlets properly installed and protected with correct BMPs?
- 10) Do drain inlets require maintenance?



	Silver Leaf SWPPP CGP							
Site Name:	Bridlewalk Phase 4 1585 F. Cluff Ln, Lake Point, UT 84074	Inspector:	Daniel Andrews					
Permit #:	UTRC06339	Inspection Frequency:	Bi-weekly -					
Date of Visit:	Aug 22, 2023, 11:01:59 AM	Last Rain Event Friday, August 18, 2023, 0.0"	Last Precipitation Thursday, August 17, 2023, 0,82	48h Forecast 85% Chance of Rain				

- 11) Are there concrete washout located onsite?
- 12) Is the site free of any washout spillage outside of the contained area?
- 13) Is each concrete washout location identified with a sign?
- 14) Are concrete washouts maintained and below 75% capacity
- 15) Are dirt and gravel stockpiles in compliance? Stockpiles need to be located off of impervious surfaces, away from surface waters and requires BMPs if it is not an active stockpile.

Yes	No	N/A
Yes	No	N/A
Yes	No	N/A
Yes	No	N/A

No

Yes

Housekeeping

- 16) Are portable toilets in compliance? Set back 10 feet from curb, staked down, secondary containment
- 17) Are dumpsters in compliance? Trash should not exceed dumpster height?
- 18) Is the site free of blowable trash? Construction debris and blowable trash onsite need to be contained.
- 19) Is dust being properly controlled onsite? Water trucks may be necessary.
- 20) Are all materials on site properly stored on site. Undercover plastic cover out of the street and off of impervious surfaces.
- 21) Does the site have a spill kit that will properly contain and clean up spills or leaks?

Yes	No	N/A
Yes	No	N/A

N/A


Discharge

22) If there is a discharge, a visual sample is required. Be sure to add a visual monitoring form to this inspection.

N/a

RUN-ON AND RUN-OFF

- 23) Where applicable, are the site Run-On flows properly controlled (i.e. waters entering the site from upslope) with BMPs to prevent contact with pollutants and to prevent erosion, and are all storm water flow structures (drainage channels, diversions, conveyance, sediment basins) FREE of erosion, sediment buildup of over 50%, or needing additional BMPs?
- 24) Are all discharge points and outfalls on or near the site FREE from sediment buildup, pollutants, and erosion, and are all surface waters on or near the site FREE from visible pollutants coming from the construction site? e.g. outfalls into a water body, retention basin outfalls, detention basin outfalls.







Silver Leaf SWPPP CGP							
Site Name:	<u>Bridlewalk Phase 4</u> 1585 F Chult Un, Lake Point, UT 84074	Inspector:	Daniel Andrews				
Permit #:	UTRC06339	Inspection Frequency:	Bi-weekly -				
		Last Rain Event	Last Precipitation	48h Forecast			
Date of Visit:	Aug 22, 2023, 11:01:59 AM	Friday, August 18, 2023, 0.0"	Thursday, August 17, 2023, 0.82"	85% Chance of Rais			

is in place more than two months out of the year) is the natural buffer or natural buffer equivalent in place on site?

26) Is the site FREE from dewatering off site perimeter boundaries, or has a dewatering permit been obtained from the state, and is proper sampling occurring?

N/A No

NOTICE OF TERMINATION

27 - Are future inspections needed?

Νo

28 - If applicable has the final inspection been scheduled with the MS4?

No

Note areas that were unsafe / non-accessible during this inspection:

N/a

Note the dates and locations of any new disturbances, excavations, major digs, areas that have been temporarily/permanently stabilized or sold:

N/a

Inspector Notes and Comments:

Inspector Notes and Comments:

Progress has been made on the oil action item as sand was placed to help soak up a portion of the spill.

NOTE: For map updating, this requires the SITE MAP to be updated with specific BMPs (including dates/locations when a BMP was added, moved, repaired, or removed with an activity description where applicable) in the SITE MAPS section when using complianceGO

Updated Maps

Map is current and up to date

Map has NOT been updated

Communication

Indicate who these inspection findings were reviewed with or sent to.

Information for site inspection review is same as question 4- Site Contact person.

No Different person site review person - (fill out below)

First Name, Last Name, Title or Role, and Company

Howard: updated on the status of the site including the current action item.



SHVERLEAFSWPPP

	Silver Leaf SWPPP CGP							
Site Name:	Bridlewalk Phase 4 1585 F. Cluff Un, Laké Polini, UT 84074	Inspector:	Daniel Andrews Bi-weekly -					
Permit #:	UTRC06339	Inspection Frequency:						
Date of Visit:	Aug 22, 2023, 11:01:59 AM	Last Rain Event Friday, August 18, 2023, 0.0"	Last Precipitation Thursday, August 17, 2023, 0.82"	48h Forecast 85% Chance of Rain				

Upload site photos:



Certification & Signatures

Signature Certification Statement::

Lectify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Electronic Signature

X Daniel Andrews

Date

August 22, 2023 at 11:06:03 AM MDT

Title

Registered Stormwater Inspector (RSI)



Silver Leaf SWPPP CGP								
Site Name:	B-idlowalk Phase 4 1585 F Cluff Ln, Lake Point, UT 84074	Inspector:	Daniel Andrews					
Permit #:	UTRC06339	Inspection Frequency:	Bi-weekly -					
Date of Visit:	Aug 22, 2023, 11:01:59 AM	Last Rain Event Friday, August 18, 2023, 0.0"	Last Precipitation Thursday, August 17, 2023, 0.82"	48h Forecast 85% Chance of Rain				

Photos







ŵ

SILVERLEAFSWPPP

Silver Leaf SWPPP CGP							
Site Name:	Bridlewalk Phase 4 1585 E Claff Ln, Lake Point, UT 84074	Inspector:	Daniel Andrews				
Permit #:	UTRC06339	Inspection Frequency:	Bi-weekly -				
Date of Visit:	Aug 22, 2023, 11:01:59 AM	Last Rain Event Friday, August 18, 2023, 0.0"	Last Precipitation Thursday, August 17, 2023, 0.82"	48h Forecast 85% Chance of Rain			

Weather History



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA), Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



Silver Leaf SWPPP CGP							
Site Name:	Bridlewalk Phase 4 1585 F. Cluff Ln, Lake Point, UT 84074	Inspector:	Daniel Andrews				
Permit #:	UTRC06339	Inspection Frequency:	Bi-weekly -				
Date of Visit:	Aug 22, 2023, 11:01:59 AM	Last Rain Event Friday, August 18, 2023, 0.0"	Last Precipitation Thursday, August 17, 2023, 0.82"	48h Forecast 85% Chance of Rain			

Action Items										
Title	ldentifler	Inspector	Date	Priority	Location	Description	Status	Closer	Notes	Photos
Concrete washout sign		Daniel Andrews	July 91, 2029	Immediate	Lot 417	The concrete washout needs a sign posted.	Closed August 22, 2023	Tom Guymon	Lot 417 has been sold off to a different owner.	PENNON.
Concrete splilage		Daniel Andrews	July 24, 2023	Immediate	Lot 43?	Concrete has been split onto the ground and needs to be cleaned up.	C osed August 22, 2029	Tom Guymon	Concrete waste has been placed in Concrete Washout. Lot 431 has been sold to a different builder. July 31, 2023: Additional spillage at lot 417 also needs to be cleaned up.	Photo i
Qii		Oaniel Andrews	June 19, 2023	immediate	North and of site.	Some oil has leated onto the ground and needs to be cleaned up.	C0660/August 22, 1023	Torn Guynton	Absorbent has been placed on the spill—no current.	£5410